

Three-Dimensional X-Ray Diffraction Microscopy

Mapping Polycrystals and their Dynamics

Bearbeitet von
Henning Friis Poulsen

1. Auflage 2004. Buch. xii, 156 S. Hardcover
ISBN 978 3 540 22330 6
Format (B x L): 15,5 x 23,5 cm
Gewicht: 930 g

[Weitere Fachgebiete > Physik, Astronomie > Thermodynamik > Festkörperphysik,
Kondensierte Materie](#)

schnell und portofrei erhältlich bei


DIE FACHBUCHHANDLUNG

Die Online-Fachbuchhandlung beck-shop.de ist spezialisiert auf Fachbücher, insbesondere Recht, Steuern und Wirtschaft. Im Sortiment finden Sie alle Medien (Bücher, Zeitschriften, CDs, eBooks, etc.) aller Verlage. Ergänzt wird das Programm durch Services wie Neuerscheinungsdienst oder Zusammenstellungen von Büchern zu Sonderpreisen. Der Shop führt mehr als 8 Millionen Produkte.

Contents

1	Introduction	1
	References	5
2	Methods for Mesoscale Structural Characterization	7
2.1	Electron and Optical Microscopy	7
2.2	X-Ray Diffraction with Low-Energy X-Rays.....	9
2.3	Conventional Bulk-Sensitive Methods	11
2.4	Hard X-Rays: Properties	12
2.5	Hard X-Ray Work Using Synchrotron Sources	14
	References	17
3	Geometric Principles	21
3.1	The Basic 3DXRD Setup	22
3.2	Diffraction Geometry	25
3.3	Representation of Crystallographic Orientation	27
3.4	Representation of Position–Orientation Space	31
3.5	Representation of Elastic Strain	33
	References	33
4	GRAINDEX and Related Analysis	35
4.1	GRAINDEX	35
4.1.1	Alternative Experimental Configurations	38
4.2	Spot Overlap	38
4.3	Analysis of Single Grains on the Basis of GRAINDEX	40
4.3.1	Grain Maps	40
4.3.2	The Orientation, Elastic Strain and Stoichiometry of a Single Grain	42
4.3.3	The Orientation Spread Within One Grain	44
4.4	Conical and Spiral Slits	44
4.5	Characterization of Large Volumes.....	46
4.6	Dynamic Experiments.....	48
	References	49

5	Orientation Mapping	51
	5.1 Image Analysis	53
	5.2 GRAINSWEEPER	54
	5.3 2D-ART	57
	5.3.1 Algebraic Formulation	57
	5.3.2 The ART Algorithm	59
	5.3.3 Results	60
	5.4 3D-ART	63
	5.5 3D-FBP	64
	5.5.1 Geometry	64
	5.5.2 The FBP Algorithm	66
	5.5.3 Results	67
	5.6 The General 6D Case	68
	5.7 Discussion	70
	References	71
6	Combining 3DXRD and Absorption Contrast Tomography	73
	6.1 Decoration of Al Grain Boundaries by Ga	75
	6.2 Plastic Strain Field	77
	6.3 Grain Mapping on the Basis of Extinction Contrast	79
	References	81
7	Multigrain Crystallography	83
	7.1 Structure Determination from Polycrystalline Data	84
	7.2 Structural Phases Appearing in ppm Concentrations	87
	References	87
8	The 3DXRD Microscope	89
	8.1 Optics	90
	8.2 Diffractometer	92
	References	94
9	Applications	95
	9.1 Polycrystalline Deformation	95
	9.1.1 The 3D Toolbox	96
	9.1.2 Grain Rotation Experiments	97
	9.1.3 Lattice Strain Experiments	100
	9.1.4 Outlook	103
	9.2 Recrystallization	103
	9.2.1 Growth Curves of Individual Grains	105
	9.2.2 Spatial Distribution of Nucleation Sites	107
	9.2.3 Outlook for the Statistical Approach	109
	9.2.4 First-Principles Studies	110
	9.3 Recovery and Nucleation	112

9.3.1	Static Recovery	114
9.3.2	Nucleation and the Emergence of New Orientations ...	117
9.3.3	Outlook	120
9.4	Peak Shape Analysis	120
9.5	Phase Transformations	123
9.5.1	Steel	124
9.5.2	Optimization of High- T_c Superconducting Tapes	127
9.6	Grain Size Distributions	130
9.6.1	Methodological Concerns	131
	References	133
10	Alternative Approaches	137
10.1	Differential-Aperture X-Ray Microscopy	137
10.2	The Moving-Area-Detector Method	140
10.3	Other Depth-Resolved X-Ray Diffraction Methods	141
10.4	Applying 3DXRD Methods to Other Sources	143
	References	144
11	Concluding Remarks	147
	References	149
	Index	151