

Cambridge University Press

0521257565 - High Vacuum Techniques for Chemical Syntheses and Measurements

P. H. Plesch

Table of Contents

[More information](#)

Contents

<i>Preface</i>	xi
<i>Acknowledgements</i>	xiii
INTRODUCTION	1
I.1. The purpose and scope of this book	1
I.2. Usages	2
I.2.1. References	2
I.2.2. Figures	2
I.2.3. Units	2
I.3. Books	3
I.4. Articles	3
1. FUNDAMENTALS	4
1.1. Reasons for using high vacuum techniques	4
1.1.1. Introduction	4
1.1.2. The Inert gas blanket	5
1.1.3. Dry-bag and dry-box	5
1.1.4. Vacuum lines	7
1.1.5. Summary	7
1.2. Theoretical considerations	8
1.2.1. What is a vacuum?	8
1.2.2. Units	9
1.2.3. General structure of a high vacuum system	9
1.2.4. Theory of pumping	10
1.2.5. Some physico-chemical features peculiar to closed systems	13
1.3. Essential skills and equipment	18
1.3.1. Skills	18
1.3.2. Equipment	20
1.3.3. Some unconventional devices	22
1.4. General comments on safety	24
<i>Reference</i>	26
	vii

Cambridge University Press

0521257565 - High Vacuum Techniques for Chemical Syntheses and Measurements

P. H. Plesch

Table of Contents

[More information](#)

viii Contents

2. THE MAIN VACUUM LINE	27
2.1. In the beginning	27
2.1.1. Guiding principles	28
2.1.2. The foundations: the bench and the frame	29
2.2. Individual components	31
2.2.1. Pumps	31
2.2.2. The cold traps	36
2.2.3. The main manifold or trunk line	39
2.2.4. Taps and Valves	39
2.2.5. Gauges	48
2.3. Building, operating, testing and dismantling the vacuum line	56
2.3.1. Building and operating	56
2.3.2. Hunting and repairing leaks	60
2.3.3. Dismantling	61
2.4. The PIEgli and Krummenacher valves	63
<i>References</i>	66
3. APPLIANCES AND PROCEDURES	67
3.1. Measuring devices and related manipulations	67
3.1.1. Burettes	67
3.1.2. Glass phials	73
3.1.3. Calibrated vessels with glass break-seals	81
3.1.4. Phial filler for large volumes	82
3.1.5. Metering compounds by volume of vapour	83
3.1.6. Dilatometers	85
3.1.7. Viscometers	94
3.1.8. UV-vis. spectroscopic measurements	95
3.1.9. NMR measurements	96
3.1.10. Conductance and other electrical measurements	97
3.2. Combined measuring devices	103
3.2.1. General considerations	103
3.2.2. Isothermal reactors	104
3.2.3. Adiabatic reactors (reaction calorimeters)	109
3.3. Stirring	112
<i>References</i>	114

Cambridge University Press

0521257565 - High Vacuum Techniques for Chemical Syntheses and Measurements

P. H. Plesch

Table of Contents

[More information](#)

	Contents	ix
4. PURIFICATION, INCLUDING DRYING		116
4.1. Preamble		117
4.2. Definitions, relevance and measures of purity		118
4.2.1. Definitions and relevance		118
4.2.2. Measures of purity		119
4.3. Cleaning the apparatus		119
4.4. The cleaning of solvents and reagents		121
4.4.1. General introduction		121
4.4.2. Physical methods		122
4.4.3. Chemical methods		126
4.4.4. Purification of catalysts		130
4.5. Determination of purity		133
4.5.1. Introduction		133
4.5.2. Effects on physical properties		134
4.5.3. Mass spectrometry		135
4.5.4. Electroanalytical methods		135
4.5.5. Detection and estimation of impurities by separation		135
4.5.6. Functional tests of purity		135
4.6. What is so special about drying?		139
4.6.1. The drying process		139
4.6.2. Some drying agents		140
4.6.3. The special hazards of drying		141
<i>References</i>		142
5. CHEMICAL OPERATIONS WITH HIGH VACUUM SYSTEMS		144
5.1. Introduction		144
5.2. Syntheses		145
5.2.1. Sodium ethoxide by the cascade method		145
5.2.2. n-Butoxytitanium trichloride		147
5.2.3. Tertiary silyl lithium compounds		148
5.2.4. 1,3-Dioxolenium salts		149
5.2.5. Electrochemical preparation of stannic chloride		150
5.2.6. Aluminium chloride		151
5.2.7. Complex salts		152

Cambridge University Press

0521257565 - High Vacuum Techniques for Chemical Syntheses and Measurements

P. H. Plesch

Table of Contents

[More information](#)

x Contents

5.3. Measurements	154
5.3.1. Electrical conductivity and UV measurements	154
5.3.2. Combined UV and ESR spectroscopy	156
5.3.3. Phase diagrams	156
5.3.4. Polymerisation kinetics by gel permeation chromatography (GPC)	158
5.3.5. Precision calorimetry	161
References	161
<i>Appendix Suppliers of vacuum equipment</i>	162
<i>A.1. General suppliers</i>	162
<i>A.2. Special equipment</i>	162
Name Index	163
Subject Index	165