

## Manufacturing Processes 1

Cutting

Bearbeitet von  
Fritz Klocke, Aaron Kuchle

1. Auflage 2011. Buch. xviii, 506 S. Hardcover  
ISBN 978 3 642 11978 1  
Format (B x L): 15,5 x 23,5 cm  
Gewicht: 943 g

[Weitere Fachgebiete > Technik > Produktionstechnik > Fertigungstechnik](#)

schnell und portofrei erhältlich bei

  
DIE FACHBUCHHANDLUNG

Die Online-Fachbuchhandlung [beck-shop.de](http://beck-shop.de) ist spezialisiert auf Fachbücher, insbesondere Recht, Steuern und Wirtschaft. Im Sortiment finden Sie alle Medien (Bücher, Zeitschriften, CDs, eBooks, etc.) aller Verlage. Ergänzt wird das Programm durch Services wie Neuerscheinungsdienst oder Zusammenstellungen von Büchern zu Sonderpreisen. Der Shop führt mehr als 8 Millionen Produkte.

# Contents

|          |                                                      |           |
|----------|------------------------------------------------------|-----------|
| <b>1</b> | <b>Introduction</b>                                  | <b>1</b>  |
| <b>2</b> | <b>Metrology and Workpiece Quality</b>               | <b>3</b>  |
| 2.1      | Manufacturing Disturbances and Manufacturing History | 3         |
| 2.2      | Measuring and Testing                                | 8         |
| 2.2.1    | Measurement Errors                                   | 9         |
| 2.2.2    | Macro- and Microgeometry of Components               | 10        |
| 2.3      | Length Testing Devices                               | 13        |
| 2.3.1    | Material Measures                                    | 13        |
| 2.3.2    | Gauges                                               | 13        |
| 2.3.3    | Indicating Measuring Instruments                     | 14        |
| 2.4      | Surface Inspection                                   | 21        |
| 2.4.1    | Surface Parameters                                   | 22        |
| 2.4.2    | Subjective Surface Inspection                        | 26        |
| 2.4.3    | Surface Measurement                                  | 27        |
| 2.5      | Inspection of the Workpiece Rim                      | 30        |
| 2.5.1    | Surface Layers                                       | 31        |
| 2.5.2    | Inspection of the Surface Rim Zone                   | 33        |
| <b>3</b> | <b>Fundamentals of Cutting</b>                       | <b>39</b> |
| 3.1      | The Cutting Part – Concepts and Terms                | 39        |
| 3.2      | Reference Systems                                    | 42        |
| 3.3      | Basic Process Variants                               | 45        |
| 3.4      | Chip Formation                                       | 47        |
| 3.4.1    | The Cutting Process                                  | 47        |
| 3.4.2    | Different Types of Chip Formation                    | 49        |
| 3.5      | Kinematic Surface Roughness                          | 54        |
| 3.6      | Mechanical and Thermal Strain on the Cutting Section | 55        |
| 3.6.1    | Influence of the Geometry of the Cutting Section     | 68        |
| 3.7      | Wear                                                 | 71        |
| 3.7.1    | Wear Mechanisms                                      | 71        |
| 3.7.2    | Causes of Wear                                       | 74        |
| 3.7.3    | Forms and Dimensions of Wear                         | 85        |

|          |                                                                   |            |
|----------|-------------------------------------------------------------------|------------|
| 3.8      | Cutting Theory . . . . .                                          | 87         |
| 3.8.1    | Shear Plane Theory . . . . .                                      | 87         |
| 3.8.2    | Application of Plasticity Theory to Cutting . . . . .             | 92         |
| <b>4</b> | <b>Cutting Tool Materials and Tools . . . . .</b>                 | <b>95</b>  |
| 4.1      | Overview of Cutting Tool Materials . . . . .                      | 95         |
| 4.1.1    | Classification of Hard Cutting Tool Materials . . . . .           | 97         |
| 4.2      | Tool Steels . . . . .                                             | 99         |
| 4.2.1    | Cold Work Steels . . . . .                                        | 100        |
| 4.2.2    | High Speed Steels . . . . .                                       | 101        |
| 4.3      | Cemented Carbides . . . . .                                       | 110        |
| 4.3.1    | Historical Development . . . . .                                  | 111        |
| 4.3.2    | Cemented Carbide Production . . . . .                             | 112        |
| 4.3.3    | Components of Cemented Carbides and Their<br>Properties . . . . . | 114        |
| 4.3.4    | Microstructure . . . . .                                          | 116        |
| 4.3.5    | Classification of Cemented Carbides . . . . .                     | 117        |
| 4.3.6    | Uncoated Cemented Carbides and Cermets . . . . .                  | 123        |
| 4.3.7    | Function Gradient Cemented Carbides . . . . .                     | 123        |
| 4.3.8    | Coated Cemented Carbides and Cermets . . . . .                    | 126        |
| 4.4      | Coatings . . . . .                                                | 127        |
| 4.4.1    | Coating Methods . . . . .                                         | 128        |
| 4.4.2    | Specific Properties of Hard Material Coatings . . . . .           | 149        |
| 4.4.3    | Substrate Pretreatment . . . . .                                  | 161        |
| 4.5      | Ceramic Cutting Tool Materials . . . . .                          | 161        |
| 4.5.1    | Cutting Ceramics . . . . .                                        | 162        |
| 4.5.2    | Superhard Non-metallic Cutting Tool Materials . . . . .           | 173        |
| 4.6      | Tool Designs . . . . .                                            | 184        |
| 4.6.1    | Solid Tools . . . . .                                             | 185        |
| 4.6.2    | Tools with Inserts . . . . .                                      | 187        |
| 4.7      | Tool Preparation . . . . .                                        | 193        |
| <b>5</b> | <b>Finite Element Method (FEM) . . . . .</b>                      | <b>197</b> |
| 5.1      | Basic Concepts of FEM . . . . .                                   | 197        |
| 5.2      | Lagrangian and Eulerian Considerations of the Continuum . . . . . | 199        |
| 5.3      | Explicit and Implicit Methods of Solution . . . . .               | 199        |
| 5.4      | Combined Thermal and Mechanical FEA . . . . .                     | 200        |
| 5.5      | Nonlinearities . . . . .                                          | 200        |
| 5.6      | Material Laws . . . . .                                           | 201        |
| 5.7      | Software . . . . .                                                | 204        |
| 5.8      | Hardware . . . . .                                                | 205        |
| 5.9      | Phases of a Finite Element Analysis (FEA) . . . . .               | 205        |
| 5.10     | The Use of FEM in Cutting Technology . . . . .                    | 206        |
| 5.10.1   | Continuous Chip Simulation . . . . .                              | 207        |
| 5.10.2   | Segmented Chip Simulation . . . . .                               | 209        |
| 5.10.3   | Simulation of the Cutting Process . . . . .                       | 212        |

|          |                                                       |     |
|----------|-------------------------------------------------------|-----|
| <b>6</b> | <b>Cutting Fluids</b>                                 | 219 |
| 6.1      | The Functions of Cutting Fluids                       | 219 |
| 6.2      | Types of Cutting Fluids                               | 219 |
| 6.2.1    | Non Water-Miscible Cutting Fluids                     | 220 |
| 6.2.2    | Water-Based Cutting Fluids                            | 221 |
| 6.3      | Guidelines on the Use of Coolant Emulsions            | 222 |
| 6.4      | Effects of the Cutting Fluid on the Machining Process | 223 |
| 6.5      | Selection of Cutting Fluids                           | 226 |
| 6.6      | Reducing or Avoiding the Use of Cutting Fluids        | 227 |
| 6.6.1    | Reducing Cutting Fluids                               | 228 |
| 6.6.2    | Minimum Quantity Cooling Lubrication (MQCL)           | 229 |
| 6.6.3    | Avoiding Cutting Fluids                               | 233 |
| <b>7</b> | <b>Tool Life Behaviour</b>                            | 237 |
| 7.1      | Determining Tool Life Parameters                      | 239 |
| 7.2      | Machinability                                         | 239 |
| 7.2.1    | Tool Life                                             | 240 |
| 7.2.2    | Resultant Force                                       | 243 |
| 7.2.3    | Surface Quality                                       | 245 |
| 7.2.4    | Chip Form                                             | 248 |
| 7.2.5    | Cutting Speed                                         | 248 |
| 7.3      | The Machinability of Steel Materials                  | 249 |
| 7.3.1    | Metallographic Constituents                           | 250 |
| 7.3.2    | Carbon Content                                        | 252 |
| 7.3.3    | Alloying Elements                                     | 254 |
| 7.3.4    | Types of Heat Treatment                               | 256 |
| 7.4      | Machinability of Various Steel Materials              | 263 |
| 7.4.1    | Machining Steels                                      | 263 |
| 7.4.2    | Case-Hardened Steels                                  | 266 |
| 7.4.3    | Heat-Treatable Steels                                 | 267 |
| 7.4.4    | Nitrided Steels                                       | 268 |
| 7.4.5    | Tool Steels                                           | 269 |
| 7.4.6    | Hardened Steels                                       | 271 |
| 7.4.7    | Non-rusting Steels                                    | 274 |
| 7.5      | Machinability of Cast Iron                            | 280 |
| 7.5.1    | White Cast Iron                                       | 280 |
| 7.5.2    | Grey Cast Iron                                        | 283 |
| 7.6      | Machinability of Non-ferrous Metals                   | 290 |
| 7.6.1    | Aluminium Alloys                                      | 290 |
| 7.6.2    | Magnesium Alloys                                      | 293 |
| 7.6.3    | Titanium Alloys                                       | 296 |
| 7.6.4    | Copper Alloys                                         | 311 |
| 7.6.5    | Nickel Alloys                                         | 314 |
| 7.7      | Machinability of Non-metals                           | 327 |
| 7.7.1    | Graphite                                              | 327 |
| 7.7.2    | Fibre-Reinforced Plastics                             | 331 |

|           |                                                      |     |
|-----------|------------------------------------------------------|-----|
| <b>8</b>  | <b>Process Design and Process Monitoring</b>         | 339 |
| 8.1       | Finding Economical Cutting Parameters                | 339 |
| 8.1.1     | Cutting Parameter Limits                             | 339 |
| 8.1.2     | Optimizing the Cutting Parameters                    | 342 |
| 8.1.3     | Calculating the Machine Hour-Rate                    | 350 |
| 8.1.4     | Planning Methods and Tools                           | 351 |
| 8.2       | Process Monitoring                                   | 352 |
| 8.2.1     | Sensors for Process Monitoring                       | 354 |
| 8.2.2     | Signal Processing and Monitoring Strategies          | 371 |
| <b>9</b>  | <b>Processes with Rotational Primary Movement</b>    | 383 |
| 9.1       | Turning                                              | 383 |
| 9.1.1     | Face Turning                                         | 385 |
| 9.1.2     | Cylindrical Turning                                  | 386 |
| 9.1.3     | Helical Turning                                      | 387 |
| 9.1.4     | Profile Turning                                      | 388 |
| 9.1.5     | Form Turning                                         | 389 |
| 9.1.6     | Further Process Variants                             | 390 |
| 9.2       | Milling                                              | 390 |
| 9.2.1     | Process Variants, Specific Characteristics and Tools | 395 |
| 9.3       | Drilling                                             | 416 |
| 9.3.1     | Profile Counterboring                                | 416 |
| 9.3.2     | Rotary Drilling                                      | 418 |
| 9.4       | Sawing                                               | 439 |
| 9.4.1     | Bandsawing                                           | 439 |
| 9.4.2     | Hacksawing                                           | 442 |
| 9.4.3     | Circular Sawing                                      | 442 |
| <b>10</b> | <b>Processes with Translatory Primary Movement</b>   | 445 |
| 10.1      | Broaching                                            | 445 |
| 10.1.1    | Face and Circular Broaching                          | 446 |
| 10.1.2    | Profile Broaching                                    | 449 |
| 10.1.3    | Form Broaching                                       | 451 |
| 10.2      | Shaving                                              | 454 |
| 10.3      | Planing and Shaping                                  | 457 |
| 10.3.1    | Face Shaping and Face Planing                        | 458 |
| 10.3.2    | Gear Shaping                                         | 459 |
| 10.3.3    | Gear Planing                                         | 466 |
|           | <b>References</b>                                    | 469 |
|           | <b>Subject Index</b>                                 | 497 |